

TEMPERATURE SENSORS




Transmitter

Input Signal : Thermocouple (Thermocouple Transmitter)
RTD (RTD Transmitter)

Output Signal : Loop Powered 4-20mA

Supply Power : Loop Powered 24-28V

GROUP		NAME, Specification	MODEL
A	Main Model Name	RTD Transmitter	DHRT
		T/C Transmitter	DHTC
		Temperature Sensor	DHS



Transmitter Wiring Diagram

